

200 N. Federal Hwy., Pompano Beach, FL 33062



**TREAGE LLC**  
**Tree and Garden Experts**

January 23, 2023

Dear George,

Enclosed please find the updated Certified Arborist Report/Tree Assessment for the property located at 200 N. Federal Hwy. in Pompano Beach, FL conducted on November 16, 2022.

Please do not hesitate to contact me if you have any further questions or needs.

Thank you,

A handwritten signature in blue ink, appearing to read "Alison Walker", with a long horizontal flourish extending to the right.

Alison Walker, ISA FL-9317A, ISA TRAQ  
Owner, Treage LLC ~ Tree and Garden Experts

200 N. Federal Hwy., Pompano Beach, Fl 33062



# ARBORIST REPORT

200 N. Federal Hwy.  
Pompano Beach, Fl 33062



Report prepared by:

Treage LLC ~ Tree and Garden Experts  
www.treage.com ~ info@treage.com ~ 786.525.7883

**AAC**

PZ22-1200039  
06/06/2023

**Assignment/Overview**

Treage LLC was contacted by George Akirtava of Elit Group to do a Certified Arborist Report/Tree Assessment at 200 N. Federal Hwy. in Pompano Beach, FL.

The site consists of two 2-story buildings and 2 separate parking areas. There are 32 trees located onsite, as well as 3 other shrubs/plants that should not be subject to regulation, that are referenced below.

**Site Visit**

A site visit was conducted on November 16, 2022. A Level 2 visual inspection of all trees was conducted and documented with photographs. Measurements of DBH, height, and canopy were taken and recorded, and the condition and location of each tree was noted. Tree measurements were taken as follows: DBH was recorded with a metal Spencer ProTape; height and canopy were estimated from the ground; and overall condition was done by visual inspection.

**Appraisal Methods**

Appraised value for all specimen trees was calculated based on Rule 14-40.030, Florida Administrative Code.

Condition ratings were based on a Level 2 inspection conducted during the site visit on November 16, 2022.

Replacement Plant Cost was calculated using the PlantAnt online application, as well as wholesale price lists from local nurseries. An average cost of the largest available size was used wherever possible/applicable.

**Disposition Table**

See Disposition Table and Mitigation Calculations on following pages.

**Disposition Table**

200 N. Federal Hwy, Pompano										
	BOTANICAL NAME	COMMON NAME	DBH (inch)	HEIGHT (ft) (oa)	SPREAD (ft)	Condition	Disposition	Appraised Value	Replacment inches	Notes
1	<i>Roystonea regia</i>	Royal Palm	14.8	35	15	Fair	Remove	2500.00		
2	<i>Sabal palmetto</i>	Sabal Palm	13	30	12	Moderate	Remove	328.13		
3	<i>Sabal palmetto</i>	Sabal Palm	19*	30	10	Poor	Remove	284.38		*with boots
4	<i>Sabal palmetto</i>	Sabal Palm	17.8	20	12	Fair	Remove	281.25		
5	<i>Sabal palmetto</i>	Sabal Palm	17.5*	25	12	Fair	Remove	328.13		*with boots
6	<i>Wodyetia bifurcata</i>	Foxtail Palm	9.5	20	10	Fair	Remove	281.25		
7	<i>Wodyetia bifurcata</i>	Foxtail Palm	8.3	20	12	Moderate	Remove	243.75		
8	<i>Phoenix roebellini</i>	Pygmy Date Palm	no ct*	4	6	Fair	Remove	9.38		*at 4.5'
9	<i>Phoenix roebellini</i>	Pygmy Date Palm	no ct*	4.5	6	Fair	Remove	9.38		*at 4.5'
10	<i>Phoenix roebellini</i>	Pygmy Date Palm	no ct*	3.5	4	Moderate	Remove	9.38		*at 4.5'
11	<i>Roystonea regia</i>	Royal Palm	19.5	60	18	Good	Remove	5312.50		
12	<i>Roystonea regia</i>	Royal Palm	16.2	55	16	Good	Remove	4781.25		
13	<i>Roystonea regia</i>	Royal Palm	19.3	55	18	Good	Remove	5062.50		
14	<i>Roystonea regia</i>	Royal Palm	18.6	50	18	Good	Remove	4250.00		
15	<i>Roystonea regia</i>	Royal Palm	16.8	60	16	Good	Remove	5312.5		
16	<i>Roystonea regia</i>	Royal Palm	17.6	55	16	Good	Remove	4781.25		
17	<i>Roystonea regia</i>	Royal Palm	19	55	18	Good	Remove	5062.50		
18	<i>Adonidia merrillii</i>	Christmas Palm	6+6+6	25	15 oa	Good	Remove	70.00		
19	<i>Ficus aurea</i>	Strangler Fig	~24	28	25	Fair	Remove	7000		
20	<i>Roystonea regia</i>	Royal Palm	~16	60	18	Fair	Remove	4000		
21	<i>Sabal palmetto</i>	Sabal Palm	~12	28	12	Fair	Remove	350		
22	<i>Ficus aurea</i>	Strangler Fig	~15	35	25	Fair	Remove		15	
23	<i>Sabal palmetto</i>	Sabal Palm	~16	25	15	Fair	Remove	350		
24	<i>Roystonea regia</i>	Royal Palm	13.5	55	16	Good	Remove	4500		
25	<i>Ficus aurea</i>	Strangler Fig	36	30	30	Poor/Hazard	Remove	6750		Severe decay
26	<i>Sabal palmetto</i>	Sabal Palm	13.8	30	12	Good	Remove	350		
27	<i>Bursera simarouba</i>	Gumbo Limbo	4.8	20	12	Fair	Remove		5	
28	<i>Ficus aurea</i>	Strangler Fig	3.6	12	8	Poor	Remove		4	Volunteer
29	<i>Bursera simarouba</i>	Gumbo Limbo	10	20	10	Poor	Remove		10	Likely volunteer
30	<i>Sabal palmetto</i>	Sabal Palm	~16	20	15	Fair	Remove	262.50		
31	<i>Ficus aurea</i>	Strangler Fig	~2+2+2	18	16	Poor	Remove		6	Volunteer
32	<i>Bursera simarouba</i>	Gumbo Limbo	4+2	20	12	Fair	Remove		6	Likely volunteer

**Mitigation Calculations**

Tree #	Species	DBH	Height (ct for palms)	Avg. Cost	Replacement Cost	Mark Up	Condition	Mitigation Cost
1	<i>Roystonea regia</i>	14.8	25	50/ft of clear trunk	1250	2.5	0.8	2500
2	<i>Sabal palmetto</i>	13	22	175	175	2.5	0.75	328.13
3	<i>Sabal palmetto</i>	19	22	175	175	2.5	0.65	284.38
4	<i>Sabal palmetto</i>	17.8	14	150	150	2.5	0.75	281.25
5	<i>Sabal palmetto</i>	17.5	18	175	175	2.5	0.75	328.13
6	<i>Wodyetia bifurcata</i>	9.5	15	150	150	2.5	0.75	281.25
7	<i>Wodyetia bifurcata</i>	8.3	15	150	150	2.5	0.65	243.75
8	<i>Phoenix roebellini</i>	no CT	3	5	5	2.5	0.75	9.38
9	<i>Phoenix roebellini</i>	no CT	3	5	5	2.5	0.75	9.38
10	<i>Phoenix roebellini</i>	no CT	3	5	5	2.5	0.75	9.38
11	<i>Roystonea regia</i>	19.5	50	50/ft of clear trunk	2500	2.5	0.85	5312.50
12	<i>Roystonea regia</i>	16.2	45	50/ft of clear trunk	2250	2.5	0.85	4781.25
13	<i>Roystonea regia</i>	19.3	45	50/ft of clear trunk	2250	2.5	0.9	5062.50
14	<i>Roystonea regia</i>	18.6	40	50/ft of clear trunk	2000	2.5	0.85	4250
15	<i>Roystonea regia</i>	16.8	50	50/ft of clear trunk	2500	2.5	0.85	5312.50
16	<i>Roystonea regia</i>	17.6	45	50/ft of clear trunk	2250	2.5	0.85	4781.25
17	<i>Roystonea regia</i>	19	45	50/ft of clear trunk	2250	2.5	0.9	5062.50
18	<i>Adonidia merrillii</i>	6+6+6	20	35	35	2.5	0.8	70
19	<i>Ficus aurea</i>	24	28	500	500	2.5	0.7	7000
20	<i>Roystonea regia</i>	16	50	50/ft of clear trunk	2000	2.5	0.8	4000
21	<i>Sabal palmetto</i>	12	20	175	175	2.5	0.8	350
23	<i>Sabal palmetto</i>	16	18	175	175	2.5	0.8	350
24	<i>Roystonea regia</i>	13.5	45	50/ft of clear trunk	2250	2.5	0.8	4500
25	<i>Ficus aurea</i>	36	30	500	500	2.5	0.45	6750
26	<i>Sabal palmetto</i>	13.8	22	175	175	2.5	0.8	350
30	<i>Sabal palmetto</i>	16	14	150	150	2.5	0.7	262.50

**Summary Mitigation Table**

Summary Table	Replacment Inches	Replacment Dollars
Hardwoods under 18"	46	
Hardwoods 18" and higher		13,750.00
Palms		48,720.00

**Observations**

**Tree #1 – *Roystonea regia*, Royal Palm** – this tree is located in the northwest corner of the property adjacent to the parking lot and next to the ROW. It is crowded with minor chlorosis and a slightly undersized canopy. Overall, it is in fair condition and is proposed for removal.

**Tree #2 – *Sabal palmetto*, Sabal Palm** – this tree is located directly east of Tree #1. It is very crowded with a pronounced curve in the upper trunk due to the crowded conditions. It is in fair condition and is proposed for removal.

**Tree #3 – *Sabal palmetto*, Sabal Palm** – this tree is located directly east of Tree #2 on the northeast side of the property. It is very crowded and has live fronds only on one side of the trunk due to severe crowding. It is in poor condition and is proposed for removal.

**Tree #4 – *Sabal palmetto*, Sabal Palm** – this tree is located directly east of Tree #3. It is very crowded and overgrown but otherwise is in fair condition. This tree is proposed for removal.

**Tree #5 – *Sabal palmetto*, Sabal Palm** – this tree is located directly east of Tree #4. It is very crowded and overgrown but otherwise is in fair condition. It is proposed for removal.



**Tree #6 – *Wodyetia bifurcata*, Foxtail Palm** – this tree is located in a small planting island on the north side of a covered valet area. It has minor chlorosis and is slightly crowded but otherwise is in fair condition with no significant defects. It is proposed for removal.

**Tree #7 – *Wodyetia bifurcata*, Foxtail Palm** – this tree is located near the east end of the planting island. It has moderate to severe chlorosis and is in overall moderate condition. This palm is proposed for removal.

**Trees #8-10 – *Phoenix roebellini*, Pygmy Date Palm** – this refers to 3 Pygmy Date palms located in the planting island with Trees #6-7. They are all under regulation size, so they should not require a permit or mitigation for their removal.



**Tree #11 – *Roystonea regia*, Royal Palm** – this tree is located next to the ROW in the southwest corner of the property. It is in good condition with no significant defects. It is proposed for removal.

**Tree #12 – *Roystonea regia*, Royal Palm** – this tree is located near the ROW on the southwest side of the property slightly east of Tree #11. It has a slightly undersized canopy, possibly due to minor nutrient deficiency, but otherwise is in good condition with no significant defects. It is proposed for removal.

**Tree #13 – *Roystonea regia*, Royal Palm** – this tree is located on the south side of the property east of Tree #12. It is in good condition with no significant defects. It is proposed for removal.

*See photos on following page.*

**Tree #14 – *Roystonea regia*, Royal Palm** – this tree is located on the south side of the property east of Trees #11-13 and just west of the concrete walkway to the covered porch area. It shows signs of minor chlorosis/nutrient deficiency, but otherwise is in good condition with no significant defects. It is proposed for removal.

**Tree #15 – *Roystonea regia*, Royal Palm** – this tree is located on the south side of the property east of the covered walkway to the covered porch area. It shows signs of very minor nutrient deficiency, but otherwise is in good condition with no significant defects. It is proposed for removal.



**Tree #16 – *Roystonea regia*, Royal Palm** – this tree is located near the southeast corner of the property. It shows very minor signs of nutrient deficiency but otherwise is in good condition. It is proposed for removal.

**Tree #17 – *Roystonea regia*, Royal Palm** – this tree is located on the south side of the property just east of the entrance to the asphalt parking lot. It is in good condition with no significant defects. It is proposed for removal.



**Tree #18 – *Adonidia merrillii*, Christmas Palm** – this refers to a cluster of 3 palms located inside of a courtyard area on the east side of the existing back building. They are slightly crowded, but otherwise in fair to good condition. They are proposed for removal.

NOTE: Tree #18 appears to be the same as Tree #11 on the survey; therefore, it has been assigned to this tree which was not included on the survey.



**Tree #19 – *Ficus aurea*, Strangler Fig** – this tree is located on the northeast side of the existing building on the east side of the property. It is crowded, overgrown, and unmaintained with minor deadwood present, but overall it is in fair condition. This tree is proposed for removal.



**Tree #20 – *Roystonea regia*, Royal Palm** – this tree is located in an overgrown cluster of vegetation on the east side of the property. It is very crowded and overgrown and could not be accessed due to its location within a fenced area. It shows signs of very minor nutrient deficiency. Overall it is in fair condition and is proposed for removal.



**Tree #21 – *Sabal palmetto*, Sabal Palm** – this tree is located on the south side of the overgrown cluster of vegetation on the east side of the property. It is very crowded and overgrown, and was inaccessible, but otherwise it is in good condition. It is proposed for removal.



200 N. Federal Hwy., Pompano Beach, Fl 33062

**Tree #22 – *Ficus aurea*, Strangler Fig** – this tree is located on the east side of the building on the east side of the property. It is inaccessible due to its location inside a fenced area. It appears to be crowded, overgrown and unmaintained with areas of slightly sparse foliage. Overall, it is in fair condition and will be removed.



**Tree #23 – *Sabal palmetto*, Sabal Palm** – this tree is located on the north side of the overgrown cluster of vegetation on the east side of the property. It is very crowded, and overgrown. Overall it is in fair condition and is proposed for removal.



**Tree #24 – *Roystonea regia*, Royal Palm** – this tree is located on the west side of the back building that is on the east side of the property. It is growing within 3.5' of the existing building. It shows very minor signs of nutrient deficiency and is in overall good condition.



**Tree #25 – *Ficus aurea*, Strangler Fig** – this tree is located on the north side of the main parking lot near the entrance to the small parking lot (Lot 17, Block 5). It has extensive internal decay at the base of the trunk and in all remaining scaffold limbs. There is decayed wood, apparent termite damage, and fruiting fungal bodies present. Based on a Level 2 inspection and using the ISA Risk Rating matrix, this tree constitutes a high risk and there are no mitigation options that can reduce its risk to moderate or less; therefore, it is recommended for consideration for removal without a permit or mitigation per FS 163.045.



*See additional photos on following page.*

200 N. Federal Hwy., Pompano Beach, Fl 33062



**Additional Trees Not on Survey**

**Tree #26 – *Sabal palmetto*, Sabal Palm** – this tree is located just east of Trees #1-5 on the northeast side of the property/parking lot. It is somewhat crowded but otherwise is in good condition. It is proposed for removal.



Treage LLC ~ Tree and Garden Experts  
www.treage.com ~ info@treage.com ~ 786.525.7883

**AAC**

PZ22-1200039  
06/06/2023

**Tree #27 – *Bursera simarouba*, Gumbo Limbo** – this tree is located east of Tree #6 in the planting island on the north side of the covered valet drop off area. It is a relatively young tree in fair condition with a slightly weak growth habit but no other significant defects. It is proposed for removal.



**Tree #28 – *Ficus aurea*, Strangler Fig** – this is a small volunteer that is growing in an overgrown cluster of Sea Hibiscus on the east side of the existing back building. It is crowded and leaning and has a weak growth habit/structure as a result. It is in poor condition and will be removed.



**Tree #29 – *Bursera simarouba*, Gumbo Limbo** – this tree is growing on the southwest corner of the cluster of overgrown vegetation on the east side of the existing back building; it is likely a volunteer. It is growing against a wooden fence and appears to have been trimmed multiple times near ground level so that it consists of multiple sprouts. There is a decay cavity near the base of the trunk. The canopy is small and sparse. Overall, this tree is in poor condition. It is proposed for removal.



**Tree #30 – *Sabal palmetto*, Sabal Palm** – this tree is located directly in front of Tree #21 on the east side of the property. It is very crowded, overgrown with vines, and unmaintained. Overall, it is in fair condition and is proposed for removal.



**Tree #31 – *Ficus aurea*, Strangler Fig** – there is at least one Strangler Fig growing in the middle of the overgrown cluster of vegetation containing Trees #20-21. It is very crowded, overgrown, inaccessible and difficult to see, but at least 3 individual trunks, each 2-3” DBH, were observed with minimal amounts of foliage visible as well. For the sake of this assessment, it is assumed that this is one tree. It is in poor condition and will be removed.



**Tree #32 – *Bursera simarouba*, Gumbo Limbo** – this tree is located on the north side of the cluster of overgrown vegetation on the east side of the property (north of Trees #20 and 23). It is crowded and overgrown with a slightly weak structure, and it is growing among utility wires. Overall, it is in fair condition and is proposed for removal.



**Additional Plants Located Onsite**

***Hibiscus tiliaceus*, Sea Hibiscus** – this refers to a large overgrown cluster of Sea Hibiscus located on the east side of the property against the southeast side of the back building. There appear to be 2 distinct individual clusters present. They are crowded, overgrown and unmaintained, and in overall moderate condition. This is more of an overgrown shrub than a tree, so it is recommended for removal without mitigation to be confirmed by the City.



***Dracaena reflexa*, Dracaena** – there is a small cluster of Dracaena located on the southwest side of the cluster of vegetation on the east side of the property (adjacent to Tree #21). It is crowded and overgrown. It is more of an overgrown shrub than a tree, so it is recommended for removal without a permit or mitigation, to be confirmed by the City.



200 N. Federal Hwy., Pompano Beach, Fl 33062

***Schefflera actinophylla*, Umbrella tree** – there are 2 clusters of Umbrella tree located on the northwest side of the overgrown cluster of vegetation on the east side of the property (adjacent to Tree #20). This is considered a nuisance species that should not require a permit or mitigation for removal, to be confirmed by the City.



### **Summary**

There are 32 trees located onsite, all of which are proposed for removal with mitigation. See appraised values in the Disposition Table and Mitigation spreadsheets.

No trees will remain and there are no trees located offsite within proximity that will be impacted by the proposed work.

Please do not hesitate to contact me if you have any further questions.

Thank you,

Alison Walker, ISA FL-9317A  
Owner, Treage LLC ~ Tree and Garden Experts