




000017

2026

2

3

4

5

6

5

7

8

9

10

11

12

13

14

15

16

17

18

19

20

21

22

23

24

25

26

27

28

29

30

31

32

33

34

35

36

37

38

39

40

41

42

43

44

45

46

47

48

49

50

51

52

53

54

55

56

57

58

59

60

61

62

63

64

65

66

67

68

69

70

71

72

73

74

75

76

77

78

79

80

81

82

83

84

85

86

87

88

89

90

Common Name

Scientific Name

DBH (inches)*

Canopy (sq. ft)

Condition Rating

Per Inch Replacement Cost**

Replacement Value***

Mitigation (DBH inches)

Disposition

Notes

Silver Buttonwood

Conocarpus sericeus

12

196

0.5

Protect in Place

Multi-leader, reduced canopy

Silver Buttonwood

Conocarpus sericeus

5

144

0.5

Protect in Place

Multi-leader, reduced canopy

Silver Buttonwood

Conocarpus sericeus

8

144

0.5

Protect in Place

Multi-leader, reduced canopy

Silver Buttonwood

Conocarpus sericeus

4

64

0.5

Protect in Place

Multi-leader, reduced canopy

Silver Buttonwood

Conocarpus sericeus

4

36

0.5

Protect in Place

Multi-leader, reduced canopy

Live Oak

Quercus virginiana

14

1440

0.6

Protect in Place

Canopy dieback

Silver Buttonwood

Conocarpus sericeus

6

64

0.5

Protect in Place

Multi-leader, reduced canopy

Silver Buttonwood

Conocarpus sericeus

5

64

0.5

Protect in Place

Multi-leader, reduced canopy

Silver Buttonwood

Conocarpus sericeus

4

64

0.5

Protect in Place

Multi-leader, reduced canopy

Gumbo Limbo

Bursera simaruba

11

672

0.5

Protect in Place

Exposed roots

Gumbo Limbo

Bursera simaruba

10

576

0.5

Protect in Place

Bark rot

Gumbo Limbo

Bursera simaruba

8

400

0.6

Protect in Place

Canopy dieback

Gumbo Limbo

Bursera simaruba

10

576

0.6

Protect in Place

Canopy dieback

Gumbo Limbo

Bursera simaruba

3

672

0.7

Protect in Place

Gumbo Limbo

Bursera simaruba

7

480

0.5

Protect in Place

Missing limbs

Gumbo Limbo

Bursera simaruba

3

480

0.7

Protect in Place

Gumbo Limbo

Bursera simaruba

7

320

0.4

Protect in Place

Bark rot

Gumbo Limbo

Bursera simaruba

7

400

0.4

Protect in Place

Bark rot, half canopy

Gumbo Limbo

Bursera simaruba

6

64

0.3

Protect in Place

Severe Canopy Dieback

Gumbo Limbo

Bursera simaruba

10

400

0.5

Protect in Place

Bark damage

Silver Buttonwood

Conocarpus sericeus

7

64

0.5

Protect in Place

Multi-leader, supported

Live Oak

Quercus virginiana

17

1936

0.4

Protect in Place

Canopy dieback, bark rot

Mahogany

Swietenia mahogani

17

1936

0.5

Protect in Place

Canopy dieback

Mahogany

Swietenia mahogani

20

1936

0.4

Protect in Place

SPECIMEN, signs of stress, bark damage

Mahogany

Swietenia mahogani

21

2304

0.4

Protect in Place

SPECIMEN, bark damage, root damage

Mahogany

Swietenia mahogani

20

1920

0.5

Protect in Place

SPECIMEN, missing limbs

Mahogany

Swietenia mahogani

16

1152

0.5

Protect in Place

Half canopy

Mahogany

Swietenia mahogani

26

1296

0.4

Protect in Place

SPECIMEN, codominant (DBH 12, and 14), poor growth habit

Mahogany

Swietenia mahogani

18

2912

0.4

Protect in Place

SPECIMEN, missing limbs, poor growth habit

Mahogany

Swietenia mahogani

16

1440

0.5

Protect in Place

Bark rot

Mahogany

Swietenia mahogani

17

864

0.4

Protect in Place

Half canopy, bark damage

Mahogany

Swietenia mahogani

15

864

0.5

Protect in Place

Half canopy

Mahogany

Swietenia mahogani

15

864

0.4

Protect in Place

Damaged roots, half canopy

Pigeon Plum

Coccoloba diversifolia

4

144

0.4

Protect in Place

Yellowing leaves, leaning

Live Oak

Quercus virginiana

8

480

0.5

Protect in Place

No tag, between electric fence

Live Oak

Quercus virginiana

11

672

0.5

Protect in Place

Exhibits signs of stress

Brazilian Pepper

Schinus terebinthifolia

3

12

0.4

Protect in Place

Invasive species

Silver Buttonwood

Conocarpus sericeus

2

8

0.4

Protect in Place

Half canopy, leaning

Silver Buttonwood

Conocarpus sericeus

4

16

0.3

Protect in Place

Codominant, canopy dieback

Live Oak

Quercus virginiana

8

320

0.5

Protect in Place

Exhibits signs of stress

Live Oak

Quercus virginiana

7

192

0.5

Protect in Place

Exhibits signs of stress

Live Oak

Quercus virginiana

6

192

0.5

Protect in Place

Exhibits signs of stress

Live Oak

Quercus virginiana

6

256

0.5

Protect in Place

Exhibits signs of stress

Live Oak

Quercus virginiana

8

256

0.5

Protect in Place

Exhibits signs of stress

Live Oak

Quercus virginiana

8

192

0.5

Protect in Place

Missing limbs

Mahogany

Swietenia mahogani

16

1936

0.5

Protect in Place

No tag, between electric fence

Mahogany

Swietenia mahogani

20

3136

0.5

Protect in Place

SPECIMEN, no tag, between electric fence

Live Oak

Quercus virginiana

7

256

0.5

Protect in Place

Exhibits signs of stress

Live Oak

Quercus virginiana

8

192

0.5

Protect in Place

Exhibits signs of stress

Live Oak

Quercus virginiana

10

288

0.5

Protect in Place

Canopy dieback

Sabal Palm

Sabal palmetto

12

144

0.5

Protect in Place

Fair condition

Sabal Palm

Sabal palmetto

12

144

0.5

Protect in Place

Fair condition

Sabal Palm

Sabal palmetto

12

144

0.5

Protect in Place

Fair condition

Sabal Palm

Sabal palmetto

13

144

0.4

Protect in Place

Poor growth habit

Sabal Palm

Sabal palmetto

13

144

0.5

Protect in Place

Leaning

Sabal Palm

Sabal palmetto

13

144

0.4

Protect in Place

Poor growth habit

Live Oak

Quercus virginiana

6

64

0.5

Protect in Place

Half canopy

Live Oak

Quercus virginiana

5

64

0.5

Protect in Place

Half canopy

Live Oak

Quercus virginiana

6

64

0.5

Protect in Place

Half canopy

Live Oak

Quercus virginiana

8

256

0.5

Protect in Place

Canopy dieback

Live Oak

Quercus virginiana

8

256

0.5

Protect in Place

Canopy dieback

Live Oak

Quercus virginiana

7

256

0.6

Protect in Place

Bark damage

Live Oak

Quercus virginiana

7

256

0.5

Protect in Place

Exhibits signs of stress

Live Oak

Quercus virginiana

11

192

0.4

Protect in Place

Codominant, leaning

Live Oak

Quercus virginiana

5

192

0.4

Protect in Place

Bark damage, canopy dieback

Silver Buttonwood

Conocarpus sericeus

5

64

0.4

Protect in Place

Multi-leader, canopy dieback

Silver Buttonwood

Conocarpus sericeus

7

144

0.4

Protect in Place

Multi-leader, missing limbs

Silver Buttonwood

Conocarpus sericeus

9

144

0.4

Protect in Place

Multi-leader, canopy dieback

Silver Buttonwood

Conocarpus sericeus

6

256

0.5

Protect in Place

Canopy dieback

Live Oak

Quercus virginiana

7

256

0.5

Protect in Place

Bark damage

Live Oak

Quercus virginiana

4

144

0.5

Protect in Place

Bark damage

Live Oak

Quercus virginiana

7

320

0.5

Protect in Place

Poor growth habit

Live Oak

Quercus virginiana

5

256

0.5

Protect in Place

Poor growth habit

Live Oak

Quercus virginiana

6

256

0.5

Protect in Place

Poor growth habit

Live Oak

Quercus virginiana

6

480

0.5

Protect in Place

Poor growth habit

Live Oak

Quercus virginiana

4

144

0.6

Protect in Place

Leaning

Live Oak

Quercus virginiana

4

256

0.5

Protect in Place

Poor growth habit

Live Oak

Quercus virginiana

5

96

0.5

Protect in Place

Poor growth habit

Silver Buttonwood

Conocarpus sericeus

8

320

0.5

Protect in Place

Bark damage

Silver Buttonwood

Conocarpus sericeus

11

576

0.4

Protect in Place

Codominant, exhibits signs of stress

Silver Buttonwood

Conocarpus sericeus

7

576

0.5

Protect in Place

Canopy dieback

Silver Buttonwood

Conocarpus sericeus

11

480

0.4

Protect in Place

Codominant, signs of stress

Silver Buttonwood

Conocarpus sericeus

13

480

0.4

Protect in Place

Multi-leader, leaning

Silver Buttonwood

Conocarpus sericeus

12

576

0.4

Protect in Place

Codominant, poor growth habit

Silver Buttonwood

Conocarpus sericeus

7

400

0.5

Protect in Place

Poor growth habit, leaning

Silver Buttonwood

Conocarpus sericeus

6

576

0.5

Protect in Place

Poor growth habit

Silver Buttonwood

Conocarpus sericeus

13

576

0.4

Protect in Place

Codominant, bark damage

Live Oak

Quercus virginiana

6

64

0.3

Protect in Place

Canopy top missing

Live Oak

Quercus virginiana

7

144

0.3

Protect in Place

Canopy top missing

Live Oak

Quercus virginiana

6

64

0.3

Protect in Place

Canopy top missing

561.687 2220

CERT NO. 6891