


EAST TERRA MAR DRIVE

SPANISH RIVER DRIVE

TERRA MAR DRIVE



SEAWALL FAILURE BENEATH THE BRIDGE

PILE CAP REPAIRS REQUIRED BENEATH THE BRIDGE

TERRA MAR DRIVE BRIDGE No. 864040

HORIZONTAL CLEARANCE CONCERN: NO PROTECTION FOR SECURITY GATES

GUARDRAIL CONCERN: DEFICIENT AND MISSING OFFSET BLOCKS

SEAWALL FAILURE BENEATH THE BRIDGE

ADA CONCERN: THE SIDEWALK ALONG THE NORTH SIDE OF THE ROAD IS ONLY LOCATED WITHIN THE BRIDGE LIMITS, THUS BOTH BEGINNING AND TERMINATING ON BOTH SIDES OF THE BRIDGE WITH NO ADVANCE WARNING (SIGNING) FOR PEDESTRIANS.

DRAINAGE CONCERN: INLET GRATE IS CLOGGED

TRIP HAZARD

HORIZONTAL CLEARANCE CONCERN: NO PROTECTION FOR UTILITY POLES WITHIN LIMITS OF SIDE STREET PARKING

BRIDGE PROTECTION MISSING

EXPANSION JOINT REPAIRS REQUIRED