DRC
PZ26-12000017
08/05/2026

Tag #	Common Name	Scientific Name	DBH (inches)*	Canopy (sq. ft)	Condition Rating	Per Inch Replacement Cost**	Replacement Value***	Mitigation (DBH inches)	Disposition	Notes
91	Pigeon Plum	*Coccoloba diversifolia*	4	64	0.5				Protect in Place	Canopy dieback
92	Pigeon Plum	*Coccoloba diversifolia*	4	64	0.5				Protect in Place	Canopy dieback
93	Mahogany	*Swietenia mahogani*	3	128	0.5				Protect in Place	Bark damage
94	Green Buttonwood	*Conocarpus erectus*	4	64	0.5				Protect in Place	Bark damage
95	Green Buttonwood	*Conocarpus erectus*	5	128	0.5				Protect in Place	Bark damage
96	Green Buttonwood	*Conocarpus erectus*	8	384	0.5				Protect in Place	Bark damage
97	Green Buttonwood	*Conocarpus erectus*	8	672	0.5				Protect in Place	Bark damage
98	Mahogany	*Swietenia mahogani*	8	320	0.6				Protect in Place	Bark damage
99	Green Buttonwood	*Conocarpus erectus*	9	480	0.6				Protect in Place	Bark damage
100	Green Buttonwood	*Conocarpus erectus*	9	672	0.6				Protect in Place	Bark damage
101	Green Buttonwood	*Conocarpus erectus*	9	768	0.6				Protect in Place	Bark damage
102	Green Buttonwood	*Conocarpus erectus*	8	720	0.4				Protect in Place	Exhibits signs of stress, no tag, behind fence
103	Live Oak	*Quercus virginiana*	4	160	0.5				Protect in Place	Bark damage, no tag, behind fence
104	Live Oak	*Quercus virginiana*	4	32	0.5				Protect in Place	Reduced canopy, no tag, behind fence
105	Live Oak	*Quercus virginiana*	4	480	0.5				Protect in Place	Canopy dieback, no tag, behind fence
106	Live Oak	*Quercus virginiana*	5	320	0.5				Protect in Place	Canopy dieback, no tag, behind fence
107	Live Oak	*Quercus virginiana*	5	576	0.5				Protect in Place	Canopy dieback, no tag, behind fence
108	Live Oak	*Quercus virginiana*	6	576	0.6				Protect in Place	Bark damage
109	Live Oak	*Quercus virginiana*	6	320	0.5				Protect in Place	Canopy dieback, no tag, behind fence
110	Live Oak	*Quercus virginiana*	4	400	0.5				Protect in Place	Canopy dieback, no tag, behind fence
111	Live Oak	*Quercus virginiana*	4	320	0.6				Protect in Place	Canopy dieback
112	Live Oak	*Quercus virginiana*	5	240	0.6				Protect in Place	Canopy dieback
113	Live Oak	*Quercus virginiana*	8	288	0.6				Protect in Place	Canopy dieback
114	Silver Buttonwood	*Conocarpus sericeius*	4	144	0.5				Protect in Place	Multi-leader, leaning
115	Silver Buttonwood	*Conocarpus sericeius*	6	144	0.5				Protect in Place	Multi-leader, leaning
116	Live Oak	*Quercus virginiana*	14	1760	0.5	$258.33	$1,808.31	14	Remove	Missing limbs
117	Sabal Palm	*Sabal palmetto*	10	144	0.5				Protect in Place	Fair condition
118	Live Oak	*Quercus virginiana*	15	1600	0.6				Protect in Place	Canopy dieback
119	Live Oak	*Quercus virginiana*	15	1440	0.6				Protect in Place	Canopy dieback
120	Live Oak	*Quercus virginiana*	6	192	0.5				Protect in Place	Leaning, canopy dieback
121	Live Oak	*Quercus virginiana*	4	144	0.4				Protect in Place	Exhibits signs of stress
122	Pigeon Plum	*Coccoloba diversifolia*	6	144	0.6				Protect in Place	Leaning
123	Pigeon Plum	*Coccoloba diversifolia*	4	144	0.6				Protect in Place	Leaning
124	Live Oak	*Quercus virginiana*	9	400	0.5				Protect in Place	Roots wrapped
125	Live Oak	*Quercus virginiana*	16	2112	0.5				Protect in Place	Exhibits signs of stress
126	Live Oak	*Quercus virginiana*	16	1760	0.5	$258.33	$2,066.64	16	Remove	Leaning
127	Live Oak	*Quercus virginiana*	14	1440	0.6				Protect in Place	Leaning
128	Silver Buttonwood	*Conocarpus sericeius*	8	64	0.3				Protect in Place	Codominant, exhibits signs of stress
129	Silver Buttonwood	*Conocarpus sericeius*	6	64	0.3				Protect in Place	Multi-leader, exhibits signs of stress
130	Live Oak	*Quercus virginiana*	9	480	0.4				Protect in Place	Exhibits signs of stress
131	Silver Buttonwood	*Conocarpus sericeius*	4	192	0.6				Protect in Place	Leaning
132	Live Oak	*Quercus virginiana*	9	400	0.5				Protect in Place	Exhibits signs of stress
133	Silver Buttonwood	*Conocarpus sericeius*	4	96	0.5				Protect in Place	Exhibits signs of stress
134	Silver Buttonwood	*Conocarpus sericeius*	2	64	0.5				Protect in Place	Canopy dieback
135	Live Oak	*Quercus virginiana*	16	1936	0.4				Protect in Place	Root rot
136	Live Oak	*Quercus virginiana*	8	672	0.5				Protect in Place	Canopy dieback
137	Live Oak	*Quercus virginiana*	20	2288	0.5				Protect in Place	SPECIMEN, limbs over road, minor canopy dieback
138	Silver Buttonwood	*Conocarpus sericeius*	4	96	0.4				Protect in Place	Codominant, leaning
139	Live Oak	*Quercus virginiana*	4	96	0.8				Protect in Place	
140	Live Oak	*Quercus virginiana*	4	64	0.8				Protect in Place	
141	Live Oak	*Quercus virginiana*	8	256	0.6				Protect in Place	Bark damage towards bottom of tree
142	Live Oak	*Quercus virginiana*	5	100	0.6				Protect in Place	
143	Live Oak	*Quercus virginiana*	12	576	0.7	$258.33	$2,169.97	12	Remove	Leaning
144	Live Oak	*Quercus virginiana*	8	400	0.7	$258.33	$1,446.65	8	Remove	
145	Live Oak	*Quercus virginiana*	13	784	0.7	$258.33	$2,350.80	13	Remove	
146	Live Oak	*Quercus virginiana*	11	256	0.7				Protect in Place	
147	Live Oak	*Quercus virginiana*	10	400	0.7				Protect in Place	
148	Live Oak	*Quercus virginiana*	9	400	0.7				Protect in Place	
149	Live Oak	*Quercus virginiana*	9	576	0.7				Protect in Place	
150	Live Oak	*Quercus virginiana*	10	400	0.7				Protect in Place	
151	Green Buttonwood	*Conocarpus erectus*	3	480	0.7				Protect in Place	
152	Silver Buttonwood	*Conocarpus sericeius*	3	480	0.7				Protect in Place	
153	Silver Buttonwood	*Conocarpus sericeius*	3	480	0.7				Protect in Place	
154	Silver Buttonwood	*Conocarpus sericeius*	3	480	0.7				Protect in Place	
155	Silver Buttonwood	*Conocarpus sericeius*	3	480	0.7				Protect in Place	
156	Silver Buttonwood	*Conocarpus sericeius*	3	480	0.7				Protect in Place	
157	Silver Buttonwood	*Conocarpus sericeius*	3	480	0.7				Protect in Place	
158	Silver Buttonwood	*Conocarpus sericeius*	3	480	0.7				Protect in Place	
159	Live Oak	*Quercus virginiana*	3	480	0.7				Protect in Place	
160	Green Buttonwood	*Conocarpus erectus*	3	480	0.7				Protect in Place	
161	Green Buttonwood	*Conocarpus erectus*	3	480	0.7				Protect in Place	
162	Green Buttonwood	*Conocarpus erectus*	3	480	0.7				Protect in Place	
163	Green Buttonwood	*Conocarpus erectus*	3	480	0.7				Protect in Place	
164	Green Buttonwood	*Conocarpus erectus*	3	480	0.7				Protect in Place	
165	Green Buttonwood	*Conocarpus erectus*	3	480	0.7				Protect in Place	
166	Green Buttonwood	*Conocarpus erectus*	3	480	0.7				Protect in Place	
167	Green Buttonwood	*Conocarpus erectus*	3	480	0.7				Protect in Place	
168	Green Buttonwood	*Conocarpus erectus*	3	480	0.7				Protect in Place	
169	Green Buttonwood	*Conocarpus erectus*	3	480	0.7				Protect in Place	
170	Green Buttonwood	*Conocarpus erectus*	3	480	0.7				Protect in Place	
171	Green Buttonwood	*Conocarpus erectus*	3	480	0.7				Protect in Place	
172	Green Buttonwood	*Conocarpus erectus*	3	480	0.7				Protect in Place	
173	Green Buttonwood	*Conocarpus erectus*	3	480	0.7				Protect in Place	
174	Green Buttonwood	*Conocarpus erectus*	3	480	0.7				Protect in Place	
175	Green Buttonwood	*Conocarpus erectus*	3	480	0.7				Protect in Place	
176	Green Buttonwood	*Conocarpus erectus*	3	480	0.7				Protect in Place	
177	Green Buttonwood	*Conocarpus erectus*	3	480	0.7				Protect in Place	
178	Green Buttonwood	*Conocarpus erectus*	3	480	0.7				Protect in Place	
179	Green Buttonwood	*Conocarpus erectus*	3	480	0.7				Protect in Place	

No.	DATE	REVISION	BY

CERT NO: 6991
WGI
561.687.2220
2035 VISTA PARKWAY, WEST PALM BEACH, FLORIDA 33411
Siyang Wen

INITIAL SUBMITTAL
JUNE 10, 2026

COASTAL RECYCLING OF POMPANO
2407 HAMMONDVILLE ROAD
POMPANO BEACH, BROWARD COUNTY, FLORIDA

TREE DISPOSITION

SHEET
TD.03
03 OF 04

PROJECT # 9413.00