

Re: ZUMIDA ERIKA 11-20-22 - Pompano Beach, FL

Lenny Vigliotti <lenny@coastalcomfortac.com>

Wed 12/14/2022 1:26 PM

To: Erika Erika <erikazahir@hotmail.com>

The existing copper refrigerant lines have a Freon leak. They currently run under a paver driveway and can not be repaired. The logical solution is to relocated the condenser and run new refrigerant lines.

Sent from my iPhone
