




TAG #	Common Name	Scientific Name	DBH (inches)	Canopy (sq. ft)	Condition Rating	Per Inch Replacement Cost**	Replacement Value***	Mitigation (DBH inches)	Disposition	Notes	Value
1270009157	Silver Buttonwood	Conocarpus sericeus	12	196	0.5				Protect in Place	Multi-leader, reduced canopy	\$755.00
05/2028	Silver Buttonwood	Conocarpus sericeus	5	144	0.5				Protect in Place	Multi-leader, reduced canopy	\$108.00
4	Silver Buttonwood	Conocarpus sericeus	8	144	0.5				Protect in Place	Multi-leader, reduced canopy	\$120.00
5	Silver Buttonwood	Conocarpus sericeus	4	64	0.5				Protect in Place	Multi-leader, reduced canopy	\$55.00
6	Live Oak	Quercus virginiana	14	1440	0.6				Protect in Place	Multi-leader, reduced canopy	\$59.00
7	Silver Buttonwood	Conocarpus sericeus	6	64	0.5				Protect in Place	Canopy dieback	\$2.175.00
8	Silver Buttonwood	Conocarpus sericeus	5	64	0.5				Protect in Place	Multi-leader, reduced canopy	\$168.00
9	Silver Buttonwood	Conocarpus sericeus	5	64	0.5				Protect in Place	Multi-leader, reduced canopy	\$108.00
10	Gumbo Limbo	Bursera simaruba	11	672	0.5				Protect in Place	Multi-leader, reduced canopy	\$108.00
11	Gumbo Limbo	Bursera simaruba	10	576	0.5				Protect in Place	Multi-leader, reduced canopy	\$750.00
12	Gumbo Limbo	Bursera simaruba	8	400	0.6				Protect in Place	Exposed roots	\$614.00
13	Gumbo Limbo	Bursera simaruba	10	576	0.6				Protect in Place	Bank rot	\$381.00
14	Gumbo Limbo	Bursera simaruba	3	672	0.7				Protect in Place	Canopy dieback	\$614.00
15	Gumbo Limbo	Bursera simaruba	7	480	0.5				Protect in Place	Canopy dieback	\$805.00
16	Gumbo Limbo	Bursera simaruba	3	480	0.7				Protect in Place	Missing limbs	\$284.00
17	Gumbo Limbo	Bursera simaruba	7	320	0.4				Protect in Place	Protect in Place	\$284.00
18	Gumbo Limbo	Bursera simaruba	7	400	0.4				Protect in Place	Bank rot, half canopy	\$250.00
19	Gumbo Limbo	Bursera simaruba	6	64	0.3				Protect in Place	Severe Canopy Dieback	\$176.00
20	Gumbo Limbo	Bursera simaruba	10	400	0.5				Protect in Place	Bank damage	\$614.00
21	Silver Buttonwood	Conocarpus sericeus	7	64	0.5				Protect in Place	Multi-leader, supported	\$238.00
22	Live Oak	Quercus virginiana	17	1936	0.4				Protect in Place	Multi-leader, bark rot	\$2,284.00
23	Mahogany	Swietenia mahoganyi	17	1936	0.5				Protect in Place	Canopy dieback, bark rot	\$2,284.00
24	Mahogany	Swietenia mahoganyi	20	1936	0.4				Protect in Place	Canopy dieback	\$2,710.00
25	Mahogany	Swietenia mahoganyi	21	2304	0.4				Protect in Place	SPECIMEN, signs of stress, bark damage	\$3,396.00
26	Mahogany	Swietenia mahoganyi	20	1920	0.5				Protect in Place	SPECIMEN, bark damage, root damage	\$3,902.00
27	Mahogany	Swietenia mahoganyi	16	1152	0.5				Protect in Place	SPECIMEN, missing limbs	\$4,713.00
28	Mahogany	Swietenia mahoganyi	28	1296	0.4				Protect in Place	SPECIMEN, missing limbs	\$2,395.00
29	Mahogany	Swietenia mahoganyi	18	2912	0.4				Protect in Place	SPECIMEN, codominant (DBH 12 and 14), poor growth habit	\$2,395.00
30	Mahogany	Swietenia mahoganyi	16	1440	0.5				Protect in Place	SPECIMEN, missing limbs, poor growth habit	\$3,653.00
31	Mahogany	Swietenia mahoganyi	17	864	0.4				Protect in Place	Bank rot	\$2,355.00
32	Mahogany	Swietenia mahoganyi	15	864	0.4				Protect in Place	Half canopy, bark damage	\$2,541.00
33	Mahogany	Swietenia mahoganyi	15	864	0.4				Protect in Place	Half canopy	\$2,088.00
34	Pigeon Plum	Coccoloba diversifolia	4	144	0.4				Protect in Place	Damaged roots, half canopy	\$1,968.00
35	Live Oak	Quercus virginiana	8	480	0.5				Protect in Place	Yellowing leaves, leaning	\$47.00
36	Live Oak	Quercus virginiana	11	672	0.5				Protect in Place	No tag, between electric fence	\$670.00
37	Brazilian Pepper	Schinus terebinthifolia	3	12	0.4				Protect in Place	Exhibits signs of stress	\$2,175.00
38	Silver Buttonwood	Conocarpus sericeus	2	8	0.3				Protect in Place	Investigative	\$21.00
39	Silver Buttonwood	Conocarpus sericeus	4	16	0.3				Protect in Place	Half canopy, leaning	\$21.00
40	Live Oak	Quercus virginiana	8	320	0.5				Protect in Place	Codominant, canopy dieback	\$59.00
41	Live Oak	Quercus virginiana	7	192	0.5				Protect in Place	Exhibits signs of stress	\$670.00
42	Live Oak	Quercus virginiana	6	192	0.5				Protect in Place	Exhibits signs of stress	\$499.00
43	Live Oak	Quercus virginiana	6	256	0.5				Protect in Place	Exhibits signs of stress	\$525.00
44	Live Oak	Quercus virginiana	8	256							

121	Live Oak	<i>Quercus virginiana</i>	4	144	0.4				Protect in Place	Exhibits signs of stress	\$123.00
122	Pigeon Plum	<i>Coccoloba diversifolia</i>	6	144	0.6				Protect in Place	Leaning	\$155.00
123	Pigeon Plum	<i>Coccoloba diversifolia</i>	4	144	0.6				Protect in Place	Leaning	\$54.00
124	Live Oak	<i>Quercus virginiana</i>	9	400	0.5				Protect in Place	Roots wrapped	\$605.00
125	Live Oak	<i>Quercus virginiana</i>	16	2112	0.5				Protect in Place	Exhibits signs of stress	\$2,895.00
126	Live Oak	<i>Quercus virginiana</i>	16	1760	0.5	\$258.33	\$2,066.64	16	Remove	Leaning	\$2,895.00
127	Live Oak	<i>Quercus virginiana</i>	14	1440	0.6				Protect in Place	Leaning	\$2,175.00
128	Silver Buttonwood	<i>Conocarpus sericeus</i>	8	64	0.3				Protect in Place	Codominant, exhibits signs of stress	\$320.00
129	Silver Buttonwood	<i>Conocarpus sericeus</i>	6	64	0.3				Protect in Place	Multi-leader, exhibits signs of stress	\$168.00
130	Live Oak	<i>Quercus virginiana</i>	9	480	0.4				Protect in Place	Exhibits signs of stress	\$864.00
131	Silver Buttonwood	<i>Conocarpus sericeus</i>	4	192	0.6				Protect in Place	Leaning	\$72.00
132	Live Oak	<i>Quercus virginiana</i>	9	400	0.5				Protect in Place	Exhibits signs of stress	\$864.00
133	Silver Buttonwood	<i>Conocarpus sericeus</i>	4	96	0.5				Protect in Place	Exhibits signs of stress	\$72.00
134	Silver Buttonwood	<i>Conocarpus sericeus</i>	2	64	0.5				Protect in Place	Canopy dieback	\$25.00
135	Live Oak	<i>Quercus virginiana</i>	16	1936	0.4				Protect in Place	Root rot	\$2,001.00
136	Live Oak	<i>Quercus virginiana</i>	8	672	0.5				Protect in Place	Canopy dieback	\$670.00
137	Live Oak	<i>Quercus virginiana</i>	20	2288	0.5				Protect in Place	SPECIMEN, limbs over road, minor canopy dieback	\$4,500.00
138	Silver Buttonwood	<i>Conocarpus sericeus</i>	4	96	0.4				Protect in Place	Codominant, leaning	\$55.00
139	Live Oak	<i>Quercus virginiana</i>	4	96	0.8				Protect in Place		\$123.00
140	Live Oak	<i>Quercus virginiana</i>	4	64	0.8				Protect in Place		\$123.00
141	Live Oak	<i>Quercus virginiana</i>	8	256	0.6				Protect in Place	Bark damage towards bottom of tree	\$670.00
142	Live Oak	<i>Quercus virginiana</i>	5	100	0.6				Protect in Place		\$226.00
143	Live Oak	<i>Quercus virginiana</i>	12	576	0.7	\$258.33	\$2,169.97	12	Remove	Leaning	\$1,967.00
144	Live Oak	<i>Quercus virginiana</i>	8	400	0.7	\$258.33	\$1,446.65	8	Remove		\$670.00
145	Live Oak	<i>Quercus virginiana</i>	13	784	0.7	\$258.33	\$2,350.80	13	Remove		\$1,108.00
146	Live Oak	<i>Quercus virginiana</i>	11	256	0.7				Protect in Place		\$924.00
147	Live Oak	<i>Quercus virginiana</i>	10	400	0.7				Protect in Place		\$1,081.00
148	Live Oak	<i>Quercus virginiana</i>	9	400	0.7				Protect in Place		\$864.00
149	Live Oak	<i>Quercus virginiana</i>	9	576	0.7				Protect in Place		\$864.00
150	Live Oak	<i>Quercus virginiana</i>	10	400	0.7				Protect in Place		\$1,081.00
151	Green Buttonwood	<i>Conocarpus erectus</i>	3	480	0.7				Protect in Place		
152	Silver Buttonwood	<i>Conocarpus sericeus</i>	3	480	0.7				Protect in Place		
153	Silver Buttonwood	<i>Conocarpus sericeus</i>	3	480	0.7				Protect in Place		
154	Silver Buttonwood	<i>Conocarpus sericeus</i>	3	480	0.7				Protect in Place		
155	Silver Buttonwood	<i>Conocarpus sericeus</i>	3	480	0.7				Protect in Place		
156	Silver Buttonwood	<i>Conocarpus sericeus</i>	3	480	0.7				Protect in Place		
157	Silver Buttonwood	<i>Conocarpus sericeus</i>	3	480	0.7				Protect in Place		
158	Silver Buttonwood	<i>Conocarpus sericeus</i>	3	480	0.7				Protect in Place		
159	Live Oak	<i>Quercus virginiana</i>	3	480	0.7				Protect in Place		
160	Green Buttonwood	<i>Conocarpus erectus</i>	3	480	0.7				Protect in Place		
161	Green Buttonwood	<i>Conocarpus erectus</i>	3	480	0.7				Protect in Place		
162	Green Buttonwood	<i>Conocarpus erectus</i>	3	480	0.7				Protect in Place		
163	Green Buttonwood	<i>Conocarpus erectus</i>	3	480	0.7				Protect in Place		
164	Green Buttonwood	<i>Conocarpus erectus</i>	3	480	0.7				Protect in Place		
165	Green Buttonwood	<i>Conocarpus erectus</i>	3	480	0.7				Protect in Place		
166	Green Buttonwood	<i>Conocarpus erectus</i>	3	480	0.7				Protect in Place		
167	Green Buttonwood	<i>Conocarpus erectus</i>	3	480	0.7				Protect in Place		
168	Green Buttonwood	<i>Conocarpus erectus</i>	3	480	0.7				Protect in Place		
169	Green Buttonwood	<i>Conocarpus erectus</i>	3	480	0.7				Protect in Place		
170	Green Buttonwood	<i>Conocarpus erectus</i>	3	480	0.7				Protect in Place		
171	Green Buttonwood	<i>Conocarpus erectus</i>	3	480	0.7				Protect in Place		
172	Green Buttonwood	<i>Conocarpus erectus</i>	3	480	0.7				Protect in Place		
173	Green Buttonwood	<i>Conocarpus erectus</i>	3	480	0.7				Protect in Place		
174	Green Buttonwood	<i>Conocarpus erectus</i>	3	480	0.7				Protect in Place		
175	Green Buttonwood	<i>Conocarpus erectus</i>	3	480	0.7				Protect in Place		
176	Green Buttonwood	<i>Conocarpus erectus</i>	3	480	0.7				Protect in Place		
177	Green Buttonwood	<i>Conocarpus erectus</i>	3	480	0.7				Protect in Place		
178	Green Buttonwood	<i>Conocarpus erectus</i>	3	480	0.7				Protect in Place		
179	Green Buttonwood	<i>Conocarpus erectus</i>	3	480	0.7				Protect in Place		
180	Gumbo Limbo	<i>Bursera simaruba</i>	3	480	0.7				Protect in Place		
181	Green Buttonwood	<i>Conocarpus erectus</i>	3	480	0.7				Protect in Place		
182	Green Buttonwood	<i>Conocarpus erectus</i>	3	480	0.7				Protect in Place		
183	Green Buttonwood	<i>Conocarpus erectus</i>	3	480	0.7				Protect in Place		
184	Green Buttonwood	<i>Conocarpus erectus</i>	3	480	0.7				Protect in Place		
185	Green Buttonwood	<i>Conocarpus erectus</i>	3	480	0.7				Protect in Place		
186	Green Buttonwood	<i>Conocarpus erectus</i>	3	480	0.7				Protect in Place		
187	Green Buttonwood	<i>Conocarpus erectus</i>	3	480	0.7				Protect in Place		
188	Green Buttonwood	<i>Conocarpus erectus</i>	3	480	0.7				Protect in Place		
189	Green Buttonwood	<i>Conocarpus erectus</i>	3	480	0.7				Protect in Place		
190	Green Buttonwood	<i>Conocarpus erectus</i>	3	480	0.7				Protect in Place		
191	Green Buttonwood	<i>Conocarpus erectus</i>	3	480	0.7				Protect in Place		
192	Green Buttonwood	<i>Conocarpus erectus</i>	3	480	0.7				Protect in Place		
193	Silver Buttonwood	<i>Conocarpus sericeus</i>	3	480	0.7				Protect in Place		
194	Green Buttonwood	<i>Conocarpus erectus</i>	3	480	0.7				Protect in Place		
195	Green Buttonwood	<i>Conocarpus erectus</i>	3	480	0.7				Protect in Place		
196	Green Buttonwood	<i>Conocarpus erectus</i>	3	480	0.7				Protect in Place		
197	Green Buttonwood	<i>Conocarpus erectus</i>	3	480	0.7				Protect in Place		
198	Green Buttonwood	<i>Conocarpus erectus</i>	3	480	0.7				Protect in Place		
199	Green Buttonwood	<i>Conocarpus erectus</i>	3	480	0.7				Protect in Place		
200	Live Oak	<i>Quercus virginiana</i>	3	480	0.7				Protect in Place		
201	Green Buttonwood	<i>Conocarpus erectus</i>	3	480	0.7				Protect in Place		
202	Green Buttonwood	<i>Conocarpus erectus</i>	3	480	0.7				Protect in Place		
203	Green Buttonwood	<i>Conocarpus erectus</i>	3	480	0.7				Protect in Place		
204	Green Buttonwood	<i>Conocarpus erectus</i>	3	480	0.7	\$110.00	\$231.00	3	Remove		
205	Green Buttonwood	<i>Conocarpus erectus</i>	3	480	0.7	\$110.00	\$231.00	3	Remove		

Per Inch Replacement Cost Calculation	
Lancaster Trees & Shrubs	\$300.00
Agri-land Solutions LLC	\$335.00
Average Cost	\$317.50
Per Inch Replacement Cost	\$258.33

Total Fee in Lieu: \$ 10,304.37



2035 Vista Parkway, West Palm Beach, FL 33411
Phone No. 866.909.2220 www.wginc.com
Cert No. 6091 - IIR No. 7055

NOT AUTHORIZED
FOR CONSTRUCTION
PRIOR TO FORMAL
CITY APPROVAL

CAD FILENAME / PART NUMBER / DATE	NO.	DATE	DESCRIPTION	REVISIONS	BY
JOB NO.	9413.00				
DRAWN BY	EW				
CHECK BY	SW				
DATE	06.10.2026				

LANDSCAPE ARCHITECT OF RECORD
SIYANG WEN, PLA
FL # LA6667556

COASTAL RECYCLING OF POMPANO

2407 HAMMONDVILLE ROAD
POMPANO BEACH, BROWARD COUNTY, FLORIDA

TREE DISPOSITION LIST

SHEET:
LD-2.01

