



COPANS TRANSIT MAINTENANCE FACILITY
PARCELS 1 & 2 (CONSTRUCTION AREAS)

NO.	SPECIES	DBH	HEIGHT	CANOPY COND.	SPREAD	RATING	NOTES AND OBSERVATIONS	RECOMMENDED DISPOSITION
001	Calistemon viminalis / Bottlebrush	11.00	25'	28'	0.2		Sub-canopy inclusion	REMOVE
002	Swietenia mahagoni / Mahogany	17.75	35'	38'	0.3			REMOVE
003	Quercus virginiana / Live Oak	8.25	25'	22'	0.5		Poor structure	REMOVE
004	Bursera simaruba / Gumbo Limbo	9.00	20'	20'	0.6		Poor structure	RELOCATE
005	Bursera simaruba / Gumbo Limbo	9.00	15'	20'	0.6		Poor structure	RELOCATE
006	Bursera simaruba / Gumbo Limbo	8.50	20'	18'	0.5			RELOCATE
007	Bucida buceras / Black Olive	13.50	30'	25'	0.2		Sub-canopy dominant, 1-sided, co-canopy	REMOVE
008	Swietenia mahagoni / Mahogany	18.00	35'	25'	0.2			REMOVE
009	Bucida buceras / Black Olive	24.00	45'	55'	0.5		Poor structure	REMOVE
010	Swietenia mahagoni / Mahogany	9.50	32'	30'	0.3		Over lifted, decay in trunk	REMOVE
011	Bursera simaruba / Gumbo Limbo	17.50	32'	30'	0.7			Remain - Protect
012	Bucida buceras / Black Olive	19.00	45'	55'	0.6		Over extended branches, co-canopy, girdling roots	REMOVE
013	Bucida buceras / Black Olive	20.00	35'	40'	0.4		co-canopy, co-dom inclusion	REMOVE
014	Bucida buceras / Black Olive	17.50	40'	25'	0.3		Co-dominant	REMOVE
015	Bucida buceras / Black Olive	18.00	32'	48'	0.5		Poor structure	REMOVE
016	Sabal palmetto / Cabbage Palm	9.00	21'	NA	0.7			REMOVE
017	Sabal palmetto / Cabbage Palm	8.00	16	NA	0.6			REMOVE
018	Sabal palmetto / Cabbage Palm	6.00	16	NA	0.4			REMOVE
019	Sabal palmetto / Cabbage Palm	7.00	16	NA	0.7			REMOVE
020	Sabal palmetto / Cabbage Palm	6.00	14	NA	0.5			REMOVE
021	Sabal palmetto / Cabbage Palm	8.00	16	NA	0.7			REMOVE
022	Sabal palmetto / Cabbage Palm	8.00	17	NA	0.6			REMOVE
023	Sabal palmetto / Cabbage Palm	8.00	14	NA	0.7			REMOVE
024	Sabal palmetto / Cabbage Palm	8.00	17	NA	0.7			REMOVE
025	Sabal palmetto / Cabbage Palm	8.00	16	NA	0.7			REMOVE
026	Sabal palmetto / Cabbage Palm	8.00	19	NA	0.4			REMOVE
027	Sabal palmetto / Cabbage Palm	8.00	17	NA	0.7			REMOVE
028	Adonidia merillii / Christmas Palm	6.00	16	NA	0.4		Trunk bleeding	REMOVE
029	Adonidia merillii / Christmas Palm	6.00	16	NA	0.4		Trunk bleeding	REMOVE
030	Adonidia merillii / Christmas Palm	6.00	14	NA	0.5		Nutritional deficiency	REMOVE
031	Adonidia merillii / Christmas Palm	6.00	16	NA	0.3		Trunk damage, nutritional deficiency, trunk bleeding	REMOVE
032	Adonidia merillii / Christmas Palm	6.00	16	NA	0.4		Trunk bleeding	REMOVE
033	Sabal palmetto / Cabbage Palm	8.00	20	NA	0.5		Sparse foliage	REMOVE
034	Sabal palmetto / Cabbage Palm	8.00	12	NA	0.5		Trunk damage	REMOVE
035	Sabal palmetto / Cabbage Palm	8.00	15	NA	0.6			REMOVE
036	Sabal palmetto / Cabbage Palm	6.00	15	NA	0.3		Trunk damage, nutritional deficiency	REMOVE
037	Sabal palmetto / Cabbage Palm	6.00	17	NA	0.6			REMOVE
038	Sabal palmetto / Cabbage Palm	8.00	15	NA	0.6			REMOVE
039	Sabal palmetto / Cabbage Palm	9.00	14	NA	0.7			REMOVE
040	Sabal palmetto / Cabbage Palm	9.00	16	NA	0.7			REMOVE
041	Sabal palmetto / Cabbage Palm	9.00	16	NA	0.7			REMOVE
042	Sabal palmetto / Cabbage Palm	9.00	20	NA	0.7			REMOVE
043	Adonidia merillii / Christmas Palm	6.00	10	NA	0.4		Nutritional deficiency	REMOVE
044	Adonidia merillii / Christmas Palm	6.00	10	NA	0.2		Nutritional deficiency	REMOVE
045	Sabal palmetto / Cabbage Palm	6.00	16	NA	0.3		Trunk damage	REMOVE
046	Sabal palmetto / Cabbage Palm	6.00	17	NA	0.6			RELOCATE
047	Sabal palmetto / Cabbage Palm	6.00	15	NA	0.7			RELOCATE
048	NUMBER NOT USED			NA				REMOVE
049	Sabal palmetto / Cabbage Palm	6.00	15	NA	0.7			REMOVE
050	Sabal palmetto / Cabbage Palm	6.00	17	NA	0.7			REMOVE
051	Sabal palmetto / Cabbage Palm	8.00	17	NA	0.7			REMOVE
052	Sabal palmetto / Cabbage Palm	8.00	17	NA	0.7			REMOVE
053	Sabal palmetto / Cabbage Palm	8.00	17	NA	0.6			REMOVE
054	Sabal palmetto / Cabbage Palm	10.00	17	NA	0.7			REMOVE
055	Sabal palmetto / Cabbage Palm	8.00	16	NA	0.5		Nutritional deficiency	REMOVE
056	Sabal palmetto / Cabbage Palm	8.00	25	NA	0.6			REMOVE
057	Sabal palmetto / Cabbage Palm	8.00	18	NA	0.7			REMOVE
058	Sabal palmetto / Cabbage Palm	8.00	16	NA	0.6			REMOVE
059	Sabal palmetto / Cabbage Palm	8.00	14	NA	0.6			REMOVE
060	Sabal palmetto / Cabbage Palm	8.00	17	NA	0.6			REMOVE
061	Delonix regia / Royal Poinciana	6.25	20'	12'	0.2		Major canopy damage, major root damage, trunk	REMOVE
062	Delonix regia / Royal Poinciana	14.00	30'	42'	0.4		Very poor structure, co-dom inclusion, decay in	REMOVE
063	Washingtonia robusta / Washingtonia	14.00	15	NA	0.7			REMOVE
064	Washingtonia robusta / Washingtonia	14.00	19	NA	0.7			REMOVE
065	Washingtonia robusta / Washingtonia	15.00	19	NA	0.7			REMOVE
066	Sabal palmetto / Cabbage Palm	10.00	19	NA	0.7			RELOCATE
067	Sabal palmetto / Cabbage Palm	12.00	19	NA	0.7			RELOCATE
068	Sabal palmetto / Cabbage Palm	9.00	17	NA	0.7			RELOCATE
069	Bucida buceras / Black Olive	15.00	40	30'	0.5		Very poor structure, non-symmetrical canopy	RELOCATE
070	Coccoloba diversifolia / Pigeon Plum	6.50	22	18'	0.6		Poor structure	RELOCATE
071	Bucida buceras / Black Olive	15.00	35	35'	0.5		Non-symmetrical canopy over lifted	REMOVE
072	Delonix regia / Royal Poinciana	18.75	20	35'	0.4		Poor structure, co-dom inclusion, heaved in past	REMOVE
073	Sabal palmetto / Cabbage Palm	13.00	23	NA	0.7			REMOVE
074	Calistemon viminalis / Bottlebrush	9.00	25	20'	0.3		Non-symmetrical canopy poor structure	REMOVE
075	Quercus virginiana / Live Oak	10.50	35	30'	0.6		Restricted roots 1 side	REMOVE
076	Sabal palmetto / Cabbage Palm	8.00	15	NA	0.7			REMOVE
077	Sabal palmetto / Cabbage Palm	8.00	17	NA	0.7			REMOVE
078	Sabal palmetto / Cabbage Palm	15.00	15	NA	0.7		Non-symmetrical canopy poor structure, restricted roots 1 side	REMOVE
079	Quercus virginiana / Live Oak	12.50	33	25'	0.3		Co-canopy, poor structure, restricted roots 1 side	REMOVE
080	Quercus virginiana / Live Oak	7.00	38	20'	0.3			REMOVE
081	Sabal palmetto / Cabbage Palm	12.00	25	NA	0.3		Pre-mature frond death	REMOVE
082	Sabal palmetto / Cabbage Palm	9.00	25	NA	0.7			REMOVE
083	Quercus virginiana / Live Oak	9.00	30	20'	0.4		Leaning, co-canopy roots 1 side	REMOVE
084	Quercus virginiana / Live Oak	11.00	30	28'	0.5			REMOVE
085	Sabal palmetto / Cabbage Palm	10.00	16	NA	0.7			REMOVE
086	Sabal palmetto / Cabbage Palm	9.00	19	NA	0.7			REMOVE
087	Sabal palmetto / Cabbage Palm	12.00	20	NA	0.7			REMOVE
088	Sabal palmetto / Cabbage Palm	12.00	15	NA	0.7			REMOVE
089	Sabal palmetto / Cabbage Palm	12.00	10	NA	0.7			REMOVE
090	Sabal palmetto / Cabbage Palm	12.00	9	NA	0.7			REMOVE
091	Quercus virginiana / Live Oak	11.50	35	33'	0.6			REMOVE
092	Sabal palmetto / Cabbage Palm	8.00	14	NA	0.6			REMOVE
093	Sabal palmetto / Cabbage Palm	12.00	18	NA	0.7			REMOVE
094	Sabal palmetto / Cabbage Palm	15.00	8	NA	0.7			REMOVE
095	Swietenia mahagoni / Mahogany	14.25	35	30'	0.6		Poor root structure	REMOVE

COPANS TRANSIT MAINTENANCE FACILITY
TREE DISPOSITION LEGEND - PARCELS 1 & 2 (CONSTRUCTION AREAS)

NO.	SPECIES	CALIPER		CANOPY COND.		NOTES AND OBSERVATIONS		RECOMMENDED
		@ DBH	HEIGHT	SPREAD	RATING		DISPOSITION	
096	Sabal palmetto / Cabbage Palm	15.00	15	NA	0.7		REMOVE	
097	Sabal palmetto / Cabbage Palm	15.00	15	NA	0.7		REMOVE	
098	Sabal palmetto / Cabbage Palm	12.00	8	NA	0.6		REMOVE	
099	Sabal palmetto / Cabbage Palm	15.00	10	NA	0.7		REMOVE	
100	Sabal palmetto / Cabbage Palm	15.00	10	NA	0.7		REMOVE	
101	Sabal palmetto / Cabbage Palm	15.00	11	NA	0.7		REMOVE	
102	Sabal palmetto / Cabbage Palm	12.00	11	NA	0.7		REMOVE	
103	Sabal palmetto / Cabbage Palm	15.00	15	NA	0.7		REMOVE	
104	Sabal palmetto / Cabbage Palm	15.00	14	NA	0.7		REMOVE	
105	Sabal palmetto / Cabbage Palm	15.00	14	NA	0.7		REMOVE	
106	Washingtonia robusta / Washingtonia	15.00	25	NA	0.7		REMOVE	
107	Washingtonia robusta / Washingtonia	15.00	32	NA	0.7		REMOVE	
108	Sabal palmetto / Cabbage Palm	12.00	21	NA	0.7		REMOVE	
109	Sabal palmetto / Cabbage Palm	10.00	21	NA	0.7		REMOVE	
110	Sabal palmetto / Cabbage Palm	10.00	17	NA	0.5	Nutritional deficiency	REMOVE	
111	Sabal palmetto / Cabbage Palm	12.00	21	NA	0.7		REMOVE	
112	Sabal palmetto / Cabbage Palm	10.00	17	NA	0.7		REMOVE	
113	Sabal palmetto / Cabbage Palm	10.00	17	NA	0.7		REMOVE	
114	Sabal palmetto / Cabbage Palm	10.00	17	NA	0.7		REMOVE	
115	Quercus virginiana / Live Oak	9.50	25	25'	0.7		REMOVE	
116	Bursera simaruba / Gumbo Limbo	10.00	25	25'	0.6		REMOVE	
117	Bursera simaruba / Gumbo Limbo	14.00	18	22'	0.6	Co-dom, girdling roots	REMOVE	
118	Sabal palmetto / Cabbage Palm	15.00	15	NA	0.7		REMOVE	
119	Sabal palmetto / Cabbage Palm	15.00	15	NA	0.7		REMOVE	
120	Quercus virginiana / Live Oak	7.00	30	26'	0.5	Co-canopy	REMOVE	
121	Quercus virginiana / Live Oak	8.00	30	32'	0.5	Co-canopy	REMOVE	
122	Sabal palmetto / Cabbage Palm	12.00	15	NA	0.7		REMOVE	
123	Sabal palmetto / Cabbage Palm	12.00	15	NA	0.7		REMOVE	
124	Sabal palmetto / Cabbage Palm	12.00	15	NA	0.7		REMOVE	
125	Quercus virginiana / Live Oak	10.00	30	25'	0.5	Co-canopy	REMOVE	
126	Quercus virginiana / Live Oak	10.00	28	22'	0.5	Co-canopy	REMOVE	
127	Quercus virginiana / Live Oak	12.00	30	25'	0.5	Co-canopy	REMOVE	
128	Sabal palmetto / Cabbage Palm	12.00	18	NA	0.7		REMOVE	
129	Sabal palmetto / Cabbage Palm	12.00	20	NA	0.7		REMOVE	
130	Sabal palmetto / Cabbage Palm	15.00	14	NA	0.7		REMOVE	
131	Quercus virginiana / Live Oak	10.00	35	26'	0.4	Dotter vine, poor structure	REMOVE	
132	Quercus virginiana / Live Oak	10.00	27	22'	0.6	Dotter vine	REMOVE	
133	Sabal palmetto / Cabbage Palm	15.00	13	NA	0.7		REMOVE	
134	Sabal palmetto / Cabbage Palm	15.00	16	NA	0.6	Nutritional deficiency	REMOVE	
135	Sabal palmetto / Cabbage Palm	15.00	16	NA	0.7		REMOVE	
136	Sabal palmetto / Cabbage Palm	15.00	13	NA	0.7		REMOVE	
137	Quercus virginiana / Live Oak	5.00	15	10'	0.3	Dotter vine, poor structure	REMOVE	
138	Quercus virginiana / Live Oak	10.00	22	22'	0.4	Dotter vine, poor structure	REMOVE	
139	Sabal palmetto / Cabbage Palm	10.00	15	NA	0.6		REMOVE	
140	Sabal palmetto / Cabbage Palm	10.00	21	NA	0.6		REMOVE	
141	Sabal palmetto / Cabbage Palm	10.00	15	NA	0.5		REMOVE	
142	Tabebuia caraiba / Yellow Tabebuia	8.00	34	25'	0.3	Co-canopy, forced main damage	REMOVE	
143	Tabebuia caraiba / Yellow Tabebuia	12.00	NA	NA	0.4		REMOVE	
144	Sabal palmetto / Cabbage Palm	8.00	18	NA	0.7		REMOVE	
145	Sabal palmetto / Cabbage Palm	8.00	15	NA	0.7		REMOVE	
146	Taxodium distichum / Bald Cypress	18.00	45	30'	0.6	Trunk damage	Remain - Protect	
147	Taxodium distichum / Bald Cypress	16.00	45	30'	0.3	Co-canopy, sparse foliage, forced main	REMOVE	
148	Sabal palmetto / Cabbage Palm	8.00	21	NA	0.6		REMOVE	
149	Sabal palmetto / Cabbage Palm	8.00	21	NA	0.4		REMOVE	
150	Sabal palmetto / Cabbage Palm	12.00	20	NA	0.6		REMOVE	
151	Sabal palmetto / Cabbage Palm	12.00	30	NA	0.7		REMOVE	
152	Sabal palmetto / Cabbage Palm	8.00	21	NA	0.6		REMOVE	
153	Sabal palmetto / Cabbage Palm	8.00	21	NA	0.6		REMOVE	
154	Sabal palmetto / Cabbage Palm	10.00	21	NA	0.6		REMOVE	
155	Sabal palmetto / Cabbage Palm	10.00	21	NA	0.6		REMOVE	
156	Quercus virginiana / Live Oak	10.00	25'	28'	0.6	Non-symmetrical canopy restricted roots	REMOVE	
157	Swietenia mahagoni / Mahogany	12.00	25	20'	0.3	restricted roots	REMOVE	
158	Swietenia mahagoni / Mahogany	12.00	22	26'	0.5	restricted roots	REMOVE	
159	Sabal palmetto / Cabbage Palm	10.00	25	NA	0.7		REMOVE	
160	Sabal palmetto / Cabbage Palm	12.00	27	NA	0.6		REMOVE	
161	Sabal palmetto / Cabbage Palm	12.00	27	NA	0.6		REMOVE	
162	Sabal palmetto / Cabbage Palm	12.00	20	NA	0.6		REMOVE	
163	Sabal palmetto / Cabbage Palm	12.00	25	NA	0.7		REMOVE	
164	Sabal palmetto / Cabbage Palm	8.00	26	NA	0.7		REMOVE	
165	Sabal palmetto / Cabbage Palm	12.00	25	NA	0.7		RELOCATE	
166	Sabal palmetto / Cabbage Palm	12.00	20	NA	0.7		RELOCATE	
167	Sabal palmetto / Cabbage Palm	12.00	25	NA	0.7		RELOCATE	
168	Sabal palmetto / Cabbage Palm	10.00	21	NA	0.7		REMOVE	
169	Sabal palmetto / Cabbage Palm	12.00	21	NA	0.6		REMOVE	
170	Sabal palmetto / Cabbage Palm	12.00	25	NA	0.7	Nutritional deficiency	RELOCATE	
171	Bucida buceras / Black Olive	20.00	35	40'	0.6		REMOVE	
172	Quercus virginiana / Live Oak	14.00	35	30'	0.5	Co-dom	REMOVE	
173	Delonix regia / Royal Poinciana	17.00	20	32'	0.6	Co-canopy	REMOVE	
174	Coccoloba diversifolia / Pigeon Plum	6.00	25	20'	0.5	Co-dom, poor structure	RELOCATE	
175	Delonix regia / Royal Poinciana	14.00	26	NA	0.7	Non-symmetrical canopy	RELOCATE	
176	Sabal palmetto / Cabbage Palm	7.00	25	NA	0.6		REMOVE	
177	Sabal palmetto / Cabbage Palm	15.00	16	NA	0.6		REMOVE	
178	Quercus virginiana / Live Oak	6.00	15	18'	0.5	Poor structure, canopy damage, girdling root, over lifted	REMOVE	
179	Quercus virginiana / Live Oak	6.00	25	25'	0.7		RELOCATE	
180	Sabal palmetto / Cabbage Palm	12.00	15	NA	0.7		RELOCATE	
181	Sabal palmetto / Cabbage Palm	15.00	15	NA	0.7		RELOCATE	
182	Sabal palmetto / Cabbage Palm	13.00	15	NA	0.7		RELOCATE	
183	Sabal palmetto / Cabbage Palm	12.00	15	NA	0.7		RELOCATE	
184	Sabal palmetto / Cabbage Palm	12.00	10	NA	0.7		RELOCATE	
185	Sabal palmetto / Cabbage Palm	12.00	18	NA	0.7		RELOCATE	
186	Sabal palmetto / Cabbage Palm	11.00	18	NA	0.7		RELOCATE	
187	Sabal palmetto / Cabbage Palm	11.00	16	NA	0.7		RELOCATE	
188	Sabal palmetto / Cabbage Palm	11.00	16	NA	0.7		RELOCATE	
189	Delonix regia / Royal Poinciana	8.00	25	NA	0.6		RELOCATE	
190	Sabal palmetto / Cabbage Palm	11.00	18	NA	0.7		REMOVE	